HORSTMAN CANADA SUPPLIER QUALITY ASSURANCE REQUIREMENTS SQAR No. 12

Page 1 of 1

The requirement outlined below, as specified on this purchase order and subsequent amendments, forms in integral part of the purchase order between Horstman Canada Inc. and the seller. The requirement shall remain in force for the duration of this purchase order only, unless deviation is authorized in writing by Horstman Canada.

12 SQAP/QAR/QAP/Drawing Inspection Report

When SQAP's, QAP's or QAR's are called out by the drawings and/or the drawings list Performance Qualification and/or Control Tests, the seller will provide Horstman Canada with a Certificate of Conformance, stating that all required tests have been successfully completed, in accordance with paragraph 17. Records of test results shall be retained by the seller for a minimum of ten years.

12.1 <u>Control Tests</u>

When Control Tests are specified, the seller shall perform the required Control Tests as defined in the SQAP/QAP/QAR or drawings. Copies of all test reports shall be submitted to Horstman Canada prior to or with the shipment, and shall be identified by the part number and purchase order number.

REVISION	DATE	DESCRIPTION	REV'D BY
В	JUNE 06/2023	REVISED TO HC	C. ALBECKER